
	Copy Approved for Release 2012/04/24 SECURITY INFORMATION RE		,
TOPIC Welzow Airfi	· · · · · · · · · · · · · · · · · · ·	. 0117	· ·
ыматан і жарамай тафоратта устра. Сутаріўся 1155 гр. маштандараная, часту гінта закага тата райгара ациона.	anti dalambah papan anggarangga kangga kangga kangga anggarangga kangga kangga kangga kangga kangga kangga kang		
EVALUATION_	DI ACE ORTAINED	- Control of the Cont	50X1-HUN
DATE OF CONTENT	- Samon Mar		
DATE OBTAINED_	DATE PREPARED	2 December 1952	Par teranings (In a inter banker) was a was a substitution before interests.
	The second secon	1' U.S. Man Subsende Solder and Publisher and Advance	i delana kalinda erisi da kalinda erisi kalinda erisi kalinda eri denen erisi kalinda eri
PAGESENCL	OSURES (NO. & TYPE)_	- MARIENTAL TARKET TARK	50X1-HUN
REMARKS		re or ann greek par a destination of the first commence of the property and the commence was an annual commenc	Flores - Layer (Baracapasa Marie Anthony Colons A. 1988 April 1984), et al. 1984 April 1984 A
	And the second of the second o	er un never grant grant gelen eine maar sels in 'n de strouwer sels als de sels ander	- When the distribute the Control of
No. 100 Me			50X1-HUN
- 100 K		<u> </u>	
to the flight co supply dump. A l taxiway between	runway and the flight control state en the runway and the southeastern ntrol station, and the other one wa arge concrete dispersal area was all the flight control station and the	ion. Two additional cotaxiway. One lane was about in line with tong the southeastern	close the
to the flight co suprly dump. A 1 taxiway between angle formed by more pronounced the taxiway in 1 station, there w capacity of 50,0 again dug out be of the container. November, recons building. Three runs from the no	on the runway and the foutheastern introl station, and the other one was all the flight control station and the the south end of the runway and the than previously reported. The spurine with the supply dump. Just south as a fuel dump in a gravel pit with 00 liters. After the tanks had been cause they were not sufficiently in a were exactly 8 meters below the subtruction work was still in progress hardstands were observed in the extent of the runway toward the south of walls consisting of concrete slabs, as was originally planned, but only	ion. Two additional cotaxiway. The lane was about in line with tong the southeastern administration building southeastern taxiway track extended parallecturate to the flight color containers, each winstalled, they were sulated. The filler neurface of the ground. On the flight control ension of the taxiway inteast.	onnecting close the close the close
to the flight consuming to the flight consuming dumps. A litaxiway between angle formed by more pronounced the taxiway in listation, there we capacity of 50,00 again dug out be of the container November, reconsibuliding. Three litruns from the notion of the shrannel properties hardstand, concrete extension other were 18 method hardstand. At an angle of about V-shaped concrete revetments were consumer to the hardstand of the har	on the runway and the foutheastern introl station, and the other one was all the flight control station and the the south end of the runway and the than previously reported. The spurine with the supply dump. Just south as a fuel dump in a gravel pit with colliters. After the tanks had been cause they were not sufficiently in a were exactly 8 meters below the subtruction work was still in progress hardstands were observed in the extert end of the runway toward the south	ion. Two additional cotaxiway. The lane was about in line with tong the southeastern administration building southeastern taxiway track extended paralled heast of the flight containers, each winstalled, they were sulated. The filler neurface of the ground, on the flight control ension of the taxiway atheast. It is were not erected and y along the rectangulate walls opposite each as the round section extension, they continued filled with any and filled with a support the section was closed by and filled with any time as the round section was closed by and filled with any time as the round section was closed by and filled with any time as the round section.	onnecting close the ay. The is ontrol with a which und the ar h n of ued at a
to the flight consuprly dump. A litaxiway between angle formed by more pronounced the taxiway in listation, there we capacity of 50,0 again dug out be of the container. November, reconsibuilding. Three literapy is a simple of the shrannel properties hardstand. Concrete extension other were 18 method hardstand. At an angle of about V-shaped concrete revetments were of were to be camouf.  1. Comments time. This would	on the runway and the foutheastern introl station, and the other one was all the flight control station and the the south end of the runway and the than previously reported. The spurine with the supply dump. Just south as a fuel dump in a gravel pit with 00 liters. After the tanks had been cause they were not sufficiently in were exactly 8 meters below the struction work was still in progress hardstands were observed in the extent end of the runway toward the south end of the rectangular end to the other end of the rectangular end that the characters. The revetment was tapering a completed. It arreared that the characters are the substituted that the characters are the substituted.	ion. Two additional cotaxiway. The lane was about in line with tong the southeastern administration building southeastern taxiway track extended parallecturate the flight co. 27 containers, each winstalled, they were sulated. The filler neurface of the ground. On the flight control ension of the taxiway atheast. It is were not erected around section to end was closed by and filled with sand. It is reported for the containers of the section of the secti	onnecting close the close the ag. The is el to ontrol with a cks On 8 which und the ar h n of ued at a Some vetments
to the flight consuprly dump. A litaxiway between angle formed by more pronounced the taxiway in listation, there we capacity of 50,0 again dug out be of the container. November, reconsiding. Three literapy lit	on the runway and the cotheratorn introl station, and the other one was arge concrete dispersal area was all the flight control station and the the south end of the runway and the than previously reported. The spurine with the supply dump. Just south as a fuel dump in a gravel pit with 00 liters. After the tanks had been cause they were not sufficiently into a were exactly 8 meters below the substruction work was still in progress hardstands were observed in the extent end of the runway toward the south end of the rectangular at the other end of the rectangular at the shrafted on the top. 2	ion. Two additional cotaxiway. The lane was about in line with tong the southeastern administration building southeastern taxiway track extended parallecturate the flight concept of the flight control ension of the ground. On the flight control ension of the taxiway at the set of the ground. It is were not erected around the walls opposite each as the round section extension, they continuously continuousl	connecting close the close the is. The is elt to control with a ccks on 8 which und the ar h n of used at a Some vetments
to the flight consuprly dump. A litaxiway between angle formed by more pronounced the taxiway in listation, there we capacity of 50,0 again dug out be of the container. November, reconsiding. Three literapy lit	on the runway and the foutheastern introl station, and the other one was arge concrete dispersal area was all the flight control station and the the south end of the runway and the than previously reported. The spurine with the supply dump. Just south as a fuel dump in a gravel pit with 00 liters. After the tanks had been cause they were not sufficiently into the ware exactly 8 meters below the substruction work was still in progress hardstands were observed in the extent end of the runway toward the south end of the rectangular end to the other end of the rectangular end the other end of the rectangular end that the shreet distance of the care between the the wall. The revetment was tapering a completed. It arreared that the shreet laged on the top. 2	ion. Two additional cotaxiway. The lane was about in line with tong the southeastern administration building southeastern taxiway track extended parallecturate the flight concept of the flight control ension of the ground. On the flight control ension of the taxiway at the set of the ground. It is were not erected around the walls opposite each as the round section extension, they continuously continuousl	onnecting close the  ag. The is el to ontrol with a  cks On 8  which  und the ar h n of ued at a Some vetments  first  50X1-HUl rse of

celzor kirfield

STORETZ



## Legend:

- 1 John chity lames
- 2 (dispersa) (area 🐪
- 3 Sour track.
- 4 Facl dump
- 5 Flight control austion
- 6 administrative hullding
- 7 Supply dump

ች β 1. 4 ጋ ± -}1125003


STOR TY


mmex 2


50X1-HUM

## Shrapnelproof Aircraft Revetment at Felzow Airfield

SECRET







## Lerend:

- Concrete-faced walls
- 2 Y-chaped protection wall
- 3 Concrete slabs
- 4 Front wall
- 5 Sand
- 6 neinforced concrete poles

STORET